





























Switching diagrams 61001–61044



Switching diagrams 61045–61062

61045

FA 6002	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36
1	X																	
2		X																

61046

FA 6002	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36	38	40
1	X																			
2		X																		

61047

FA 6002	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36	38	40	42	44
1	X																					
2		X																				

61048

FA 6002	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36	38	40	42	44	46	48
1	X																							
2		X																						

61049

FA 6005	2	4	6
1	X		
2		X	
3			X

61050

FA 6006	2	4	6	8
1	X			
2		X		
3			X	
4				X

61051

FA 6007	2	4	6	8	10
1	X				
2		X			
3			X		
4				X	
5					X

61052

FA 6008	2	4	6	8	10	12
1	X					
2		X				
3			X			
4				X		
5					X	
6						X

61053

FA 3015	2	4	6	8	10	12	14
1	X						
2		X					
3			X				
4				X			
5					X		
6						X	
7							X

61054

FA 3016	2	4	6	8	10	12	14	16
1	X							
2		X						
3			X					
4				X				
5					X			
6						X		
7							X	
8								X

61055

FA 3017	2	4	6	8	10	12	14	16	18
1	X								
2		X							
3			X						
4				X					
5					X				
6						X			
7							X		
8								X	
9									X

61056

FA 3018	2	4	6	8	10	12	14	16	18	20
1	X									
2		X								
3			X							
4				X						
5					X					
6						X				
7							X			
8								X		
9									X	
10										X

61057

FA 3019	2	4	6	8	10	12	14	16	18	20	22
1	X										
2		X									
3			X								
4				X							
5					X						
6						X					
7							X				
8								X			
9									X		
10										X	
11											X

61058

FA 3020	2	4	6	8	10	12	14	16	18	20	22	24
1	X											
2		X										
3			X									
4				X								
5					X							
6						X						
7							X					
8								X				
9									X			
10										X		
11											X	
12												X

61059

FA 6020	2	4
0		
1	X	
2		X

61060

FA 6021	2	4	6
0			
1	X		
2		X	
3			X

















61061

FA 6022	2	4	6	8
0				
1	X			
2		X		
3			X	
4				X

















61062

FA 6023	2	4	6	8	10
0					
1	X				
2		X			
3			X		
4				X	
5					X















Switching diagrams 61063–61082




Switching diagrams 61083–61111



Switching diagrams 61112–61137


























Switching diagrams 61151–61215

























61217


FA 6014

































Switching diagrams 61314–61330



Switching diagrams 61331 – 61485



Switching diagrams 61625–61917



Switching diagrams 61918–61932

61918

FA 9078

	2	4	6	8	10	12	14	16
1 ON	X	X	X	X	X	X	X	X

61919

FA 9078

	2	4	6	8	10	12	14	16
1 ON	X	X	X	X	X	X	X	X

61920

FA 3009

	2	4	6
0			
1	X		
2		X	
3	X	X	
4			X
5	X		
6		X	
7	X	X	X

61921

FA 3009

	2	4	6
0	X	X	X
1		X	
2	X		
3		X	
4	X	X	
5			X
6	X		
7		X	

61922

FA 3009

	2	4	6	8	10	12
0					X	X
1	X					
2		X			X	
3	X	X				X
4			X		X	
5	X			X		
6		X		X		
7	X	X	X			

61923

FA 3013

	2	4	6	8
0				
1	X			
2		X		
3	X	X		
4			X	
5	X			
6		X		
7	X	X	X	
8				X
9	X			
10		X		
11	X	X	X	

61924

FA 3013

	2	4	6	8	10	12	14	16
0					X	X	X	X
1	X							
2		X			X			
3	X	X					X	
4			X		X			
5	X			X		X		
6		X		X				
7	X	X	X				X	
8				X	X	X		
9	X				X	X		
10		X		X			X	
11	X	X	X	X	X	X		

61930

FA 3011

	2	4	6	8
0				
1	X			
2		X		
3	X	X		
4			X	
5	X			
6		X		
7	X	X	X	
8				X
9	X			

61931

FA 3011

	2	4	6	8
0	X	X	X	X
1		X		
2	X			
3		X		
4	X	X		
5			X	
6	X			
7		X		X
8	X	X	X	
9		X	X	

61932

FA 3011

	2	4	6	8	10	12	14	16
0	X				X	X	X	X
1		X						
2			X		X			
3	X	X					X	
4			X		X			
5	X			X		X		
6		X		X				
7	X	X	X				X	
8				X	X	X		
9	X		X	X	X	X		